CENTRAL BACKPLANE (2 OF 3)



REPLACED TRIPLE INPUT AND: TIMING ISSUES?